




# AUXILIARY FUEL TANKS INSTALLED ON VH-RON

The aircraft is equipped with two auxiliary fuel tanks, which are installed in the fwd section of the aft cargo behind a false bulkhead. Refer to details below for installation locations.



The auxiliary fuel tank specifications are as follows.

| Auxiliary fuel tank - forward |           |          |                       |
|-------------------------------|-----------|----------|-----------------------|
| Manufacturer                  | Rogerson  |          |                       |
| Part Number                   | 7322100-1 |          |                       |
| Serial Number                 | 043       |          |                       |
| Max Allowable Fuel Quantity   | 3,493 lbs | 1,584 Kg |                       |
|                               | Hours     | Cycles   | Time                  |
| A/C Time @ Fit                | 31522     | 13154    | 16 January 2004       |
| Tank Time Since Inst          | 5604      | 2777     | 24 Months             |
| Tank Time since Repair        | 7059      | 3593     | 71 Months             |
| Tank Time Since New           | 7059      | 3593     | 71 Months (5.9 years) |
| Overhaul Interval             |           |          | 10 Years              |
| A/C Time Due Overhaul         |           |          | 06 February 2010      |

| Auxiliary fuel tank - aft   |           |          |                 |
|-----------------------------|-----------|----------|-----------------|
| Manufacturer                | Rogerson  |          |                 |
| Part Number                 | 7322500-1 |          |                 |
| Serial Number               | 026       |          |                 |
| Max Allowable Fuel Quantity | 3,493 lbs | 1,584 Kg |                 |
|                             | Hours     | Cycles   | Time            |
| A/C Time @ Fit              | 31522     | 13154    | 16 January 2004 |
| Tank Time Since Inst        | 5604      | 2777     | 24 Months       |
| Tank Time since Repair      | 7059      | 3593     | 65 Months       |
| Tank Time Since New         | 505604    | 16214    |                 |
| Overhaul Interval           |           |          | 10 Years        |
| A/C Time Due Overhaul       |           |          | 16 August 2010  |

IBA have confirmed that the tanks are installed, however they could not be sighted as the panels could not be removed at the time of the inspection. Refer to detail below.

